9	œ		O	v	4	ω	2		ITEM
						_	10		PROIRITY
2 GROUNDS	2 GROUNDS	2 GROUNDS	2 MIDDLE	MIDDLE & ELEMENTARY	1 ALL	ELEMENTARY	ELEMENTARY	ELEMENTARY	SCHOOL
replace baseball backstop	replace dugout roofs	fertilize, seed, etc	pave parking lot north side	UPGRADE FIRE ALARM AND SPRINKLER SYSTEMS BRINGING THEM UP TO CODE	RUILDING SECURITY	Rose wing REPLACE ROOF	Elementary Rose wing roof where it abutts to the first gr wing needs repair.	Repair Rose wing Facia . Will require lead abatement	DESCRIPTION
						1			
		\$35,000.00	\$59,350.00		حىن بىلىچ				COST
			2/25/2008. REFERRED CLIFF GREEN AND SONS 2-11-14. ESTIMATE IN 1 WEEK.	CONTRACTOR WALK THROUGH 2-27-14		estimate Garland ADD ITEMS 1,2,TO THIS PROJECT	ADD TO ITEM 3	ADD TO ITEM 3	NOTE
			area is used for play ground.Suggest changing traffic pattern. Mr. Tanner referred this to town engineer. Have a suggested layout for review.	Parts for both systems are no longer manufactured. Also several areas especially in the Elementary school are	extremely inadequate	1989 ROOF Needs replacing 5764 sq. ft. \$9 to \$9.50 for shingles. \$14 to \$15 per sq. ft metal. (recommended if solar panels)	cost estimate \$2800	abatement cost \$3800, does not include repair	REMARKS

	X
New York	
111 111	
1	

not thermo pane glass . Some frames damaged			upgrade windows in old section to energy efficient window(29 units)	MIDDLE	13. 80.
installed in 1969. should be replaced with a new smaller more efficient unit.			replace 1 electric hotwater heater. 520 gal. 3 ph 480V 60KW. Year 1969	MIDDLE	17
poor construction toilets are hung on sheetrock wall an wall is giving way.Will require removal of toilets and partitions			5/6 & 7/8gr lavs walls need repair	MIDDLE	16
20 yr 2019			REPLACE 4TH GR ROOF	ELEMENTARY	15
poor condition			Rose wing parking lot	ELEMENTARY	14
20 yr 2015 INSTALLED 1995 WARRANTY 15YEARS			REPLACE ROOF	2 ELEMENTARY F	13
20 YR 2015 INSTALLED 1995 WARRANTY 20 YEARS			REPLACE ROOF		12
			repair/replace baseball field fence and add covering to top rail	2 GROUNDS C	1
energy savings.present stats are pneumatic and they are not functioning correctly.			EMS FOR 3rd&4th gr classrooms	2 ELEMENTARY	10
REMARKS	NOTE	COST	DESCRIPTION	SCHOOL	ITEM PROIRITY

27	26	25	24	23	22	21	20	19	ITEM PROIRITY
GROUNDS	GROUNDS	GRÓUNDS	GROUNDS	GROUNDS	GROUNDS	GROUNDS	MIDDLE	MIDDLE	TY SCHOOL
clear tree area north side of cafeteria.	clear tree area between Middle school parking lot soccer field . Security and out of control.	clear tree area between Middle school parking lot and rose wing lot . Security and out of control	replace John Deere with 4wheel drive & plow,loader	John Deere transmission repair 5th gear OR	remove all damaged curbing & landscape areas damage by winter snow removal	X MARK purchased 2000 -over 2000 hrs	Cabinet Unit heater main entrance	corridor tile repair	DESCRIPTION
			\$20,000.00	\$3,000.00			\$10,000.00	\$ 3,459.50	COST
			estimated	estimated	estimated	10 years old	estimated	proposal 3-25-8	NOTE
				Purchased in 1985	grade to road and eliminate curbing	replaced engine 2009	inadequate heat at main entrance		REMARKS

9 5		2	33	83	ü	30	29	28	
ALL		ELEMENTARY	ELEMENTARY	ELEMENTARY	ELEMENTARY	ELEMENTARY	ELEMENTARY	GROUNDS	PROIRITY SCHOOL
TELEPHONE AND VIDEO UPGRADES		Install gutters on roof 4th gr and cafeteria.	Widen portions of driveway from school street to the Pre school entrance	3rd & 4th Gr Classrooms have ACBM floor tiles and wall coverings	4th gr rm C11 exit door	mechanical ventillation for Rose wing. Presently there isn't any	mechanical ventillation for 1st,2 nd, 3 rd, and 4 th gr. Presently there is only exhaust air.	improve landscaping in front of middle school and upper soccer field near road	DESCRIPTION
.17			\$4,200.00						COST
			\$4,200.00 proposal 7-13-9			estimated	estimated		NOTE
	into 3rd gr lavs	See pictures . Brick wall rear of building coverd with mold . Also water leaking	school buses unable to stay on drive causing cracking of surface near edges .	Some rooms have loose tiles. See "6Month Reassessment Report"	this is the only room in 4th gr that has an exit door that opens directly outside. The door has not functioned in several	need to open windows	need to open windows		REMARKS

On	4	ယ	N		ITEM
					PROIRITY
				ALL	
				Convert Lav fixtures to touchless and electric hand dryers.	DESCRIPTION
					COST
					NOTE
					REMARKS