

Brooklyn IW&WC Site Walk

Date: 7/20/21

Scheduled Time: 5:15PM

Location: 35 Kara Road

Owner: Deborah S. Love

Attendees: Demian Sorrentino, Jason Burgess, Richard Oliverson, Lester Philips

It is determined that no quorum is present.

Commissioners gathered in the driveway and met the owner's husband Lester Phillips. Site walk started at 5:20PM. Commissioners viewed the recently placed fill material at the top of the hill and the embankment down towards the southerly abutter's property. Mr. Philips guided commissioners down the hill to the flat area adjacent Creamery Brook, commissioners observed the logs on the ground and wood chips on the berm. Commissioners then walked around the westerly pond, then back between the ponds where they observed a portion of the gravel path had had been eroded. Commissioners observed the driveway at the end of Kara drive that is covered in concrete. Commissioners walked back to the flat area adjacent Creamery Brook and observed the location where surface water drains from this flat area into the riparian wetlands, then walked back up the bank to the parking area.

Site walk ended at 5:38PM.

Respectfully Submitted – Demian A. Sorrentino, IW&WC Member.