

Brooklyn Land Use Department

69 South Main Street
Brooklyn CT 06234
(860) 779-3411 x 31

Inland Wetlands

Zoning Enforcement

Blight Enforcement _____

SITE INSPECTION NUMBER

1 2 3 4 5

11 Kathleen Dr.

7-1-21

Address

Date

The goal is to make a nice lawn on the left side of the house (facing from driveway) to match the e. lawn on the right side. A big oak was removed from 20'+/- from the back left corner of the house. It was removed ^{by a tree professional.} A second tree was cut by the tree professional + the tips of the branches went over the property line at 9 Kathleen Dr. The owner of 9 Kathleen Dr called the police + the police said to stay away from the property line + not to speak to Al Sharpe or they could be arrested. The remains of a rock garden + pea stone were pushed into ^{behind the house,} the woods. The goal is to level out the piles of fill to flatten the edge of the new lawn. No wetlands are visible from the limit of work. The disturbed area will have ~~some~~ a small amount of additional loam spread and then hydroseeded by Labor ~~to~~ Day. No wetlands impacts were observed or anticipated.

Commission Representative

M. Washburn

Owner or Authorized Signature

Rose M. Jones-Findley

Existing lawn right side of house



left side of house where lawn is proposed




Rear yard where lawn is proposed



Fill to be levelled for edge of lawn



Fill to
be levelled
to create
smooth
edge of lawn
where backyard
meets the woods.



11 Kathleen Drive

Limit of work relative to wetlands

Legend

- 11 Kathleen Dr
- Alluvial and Floodplain Soils
- CT600
- Feature 1
- Poorly Drained and Very Poorly Drained Soils

Limit of work
relative to
wetlands.
160ft +/-

Quinebaug River Trail

Kathleen Dr

Google Earth

© 2021 Google

300 ft

