



Brooklyn Land Use Department

69 South Main Street
Brooklyn CT 06234
(860) 779-3411 x 31

Inland Wetlands Zoning Enforcement _____ Blight Enforcement _____

SITE INSPECTION NUMBER

1 2 3 4 5

35 Kara Road

4/21/21

Address

Date

I inspected at the request of Rick Ives, who received complaints about trucks bring loads of fill. I met Les Philips, who showed me the site. While I was on site, 2 loads of fill arrived, one from Cliff Green + Sons and one from J+B Transportation. Mr. Philips told them to leave and not bring any more fill. Mr. Philips said that the fill was coming from the Big Y in Danielson, where a retaining wall is being demolished. There is some wetlands vegetation at the toe of the fill which is at least 15-20 feet deep. There is also obviously very recent wetland filling at the toe of the slope where many cubic yards of wood chips have been placed. The GIS map confirms fill is in wetlands.

Commission Representative M. Washburn

Owner or Authorized Signature _____